

ROLLING THUNDER LLC
22231 Marine View Drive South
Kent, Washington 98198 206 870-7482

CHIEF 1999-2000

INDIAN MOTORCYCLE RECALL

Make : INDIAN **Model :** CHIEF **Year :** 1999

Build Dates : 19990301 - 20000830

NHTSA CAMPAIGN ID Number : 02V144000

Date Owner's Notified:	Date Received by ODI:	Date Added to Databse:
20020531	20020530	20020603

Manufacturer's Involved: INDIAN MOTORCYCLE COMPANY

Manufacturer's Responsible for the Recall: INDIAN MOTORCYCLE COMPANY

Manufacturer Campaign Number: IMCSB-040

Component: STEERING:WHEEL AND HANDLE BAR

Potential Number Of Units Affected : 4765

Summary:

ON CERTAIN MOTORCYCLES, THE HANDLE BAR RISER TOP CLAMP COULD ALLOW EXCESSIVE MOVEMENT OF THE HANDLE BARS.

Consequence:

LOSS OF CONTROL OF THE MOTORCYCLE COULD OCCUR, INCREASING THE RISK OF A CRASH.

Remedy:

DEALERS WILL FIT THE MOTORCYCLES WITH A NEW RISER TOP CLAMP. OWNER NOTIFICATION BEGAN MAY 31, 2002. OWNERS WHO TAKE THEIR VEHICLES TO AN AUTHORIZED DEALER ON AN AGREED UPON SERVICE DATE AND DO NOT RECEIVE THE FREE REMEDY WITHIN A REASONABLE TIME SHOULD CONTACT INDIAN MOTORCYCLE AT 1-408-846-7228.

Report Initiator: ODI

Vehicles Report

Regulation Part Number: **Federal Motor Vehicle Safety Standard Number:**

Notes:

CUSTOMERS CAN ALSO CONTACT THE NATIONAL HIGHWAY TRAFFIC SAFETY ADMINISTRATION'S AUTO SAFETY HOTLINE AT 1-888-DASH-2-DOT (1-888-327-4236).