

ROLLING THUNDER LLC
22231 Marine View Drive South
Des Moines, Washington 98198
(206) 870-7482
www.rollingthunderllc.com

CHIEF 1999-2000

Make : INDIAN **Model :** CHIEF **Year :** 1999

Build Dates : 19990601 - 20001031

NHTSA CAMPAIGN ID Number : 02V124000

Date Owner's Notified: **Date Received by ODI:** **Date Added to Database:**
20020508 20020503 20020514

Manufacturer's Involved: INDIAN MOTORCYCLE COMPANY

Manufacturer's Responsible for the Recall: INDIAN MOTORCYCLE COMPANY

Manufacturer Campaign Number: IMCSB-039

Component: SUSPENSION:REAR

Potential Number Of Units Affected : 4590

Summary:

ON CERTAIN MOTORCYCLES EQUIPPED WITH REAR SHOCK ABSORBERS MADE BY SWAY-A-WAY, THE BOLTS THAT MOUNT THE REAR SHOCK ABSORBERS TO THE SWING ARM COULD BREAK.

Consequence:

THIS COULD RESULT IN THE COLLAPSE OF THE REAR SUSPENSION, INCREASING THE RISK OF A CRASH.

Remedy:

DEALERS WILL INSPECT THE REAR SHOCK ABSORBERS AND REPLACE THEM IF NECESSARY. OWNER NOTIFICATION IS EXPECTED TO BEGIN DURING MAY 2002. OWNERS WHO TAKE THEIR VEHICLES TO AN AUTHORIZED DEALER ON AN AGREED UPON SERVICE DATE AND DO NOT RECEIVE THE FREE REMEDY WITHIN A REASONABLE TIME SHOULD CONTACT INDIAN AT 1-408-846-7228.

Report Initiator: ODI

Vehicles Report

Regulation Part Number: **Federal Motor Vehicle Safety Standard Number:**

Notes:

(1-888-327-4236).