

ROLLING THUNDER LLC  
22231 Marine View Drive South  
Des Moines, Washington 98198  
(206) 870-7482  
[www.rollingthunderllc.com](http://www.rollingthunderllc.com)

SCOUT 2001

**Make :** INDIAN                      **Model :** SCOUT                      **Year :** 2001

**Build Dates :** 20000525 - 20000728

**NHTSA CAMPAIGN ID Number :** 00V214000

**Date Owner's Notified:**              **Date Received by ODI:**              **Date Added to Databse:**  
20000914                              20000807                              20000811

**Manufacturer's Involved:** INDIAN MOTORCYCLE COMPANY

**Manufacturer's Responsible for the Recall:** INDIAN MOTORCYCLE COMPANY

**Manufacturer Campaign Number:**

**Component:** ELECTRICAL SYSTEM:BATTERY:CABLES

**Potential Number Of Units Affected :** 184

**Summary:**

VEHICLE DESCRIPTION: MOTORCYCLES. POSSIBLE POSITIVE BATTERY CABLE CHAFFING CAN CAUSE THE CABLE TO GROUND TO FRAME, ALLOWING POSSIBLE INTERRUPTION TO THE IGNITION SYSTEM. MOTORCYCLE CAN CRANK, BUT NOT START.

**Consequence:**

WITHOUT THE ADDITIONAL INSULATION, THE MOTORCYCLE POSES A RISK TO SAFETY, WITH POSSIBLE INTERRUPTION OF THE IGNITION SYSTEM.

**Remedy:**

DEALERS WILL INSTALL ADDITIONAL INSULATION ON THE POSITIVE BATTERY CABLE.

**Report Initiator:** MFR

**Vehicles Report**

**Regulation Part Number:**      **Federal Motor Vehicle Safety Standard Number:**

**Notes:**

CUSTOMERS CAN ALSO CONTACT THE NATIONAL HIGHWAY TRAFFIC SAFETY ADMINISTRATION'S AUTO SAFETY HOTLINE AT 1-888-DASH-2-DOT (1-888-327-4236).