

ROLLING THUNDER LLC
22231 Marine View Drive South
Des Moines, Washington 98198
(206) 870-7482
www.rollingthunderllc.com

SCOUT 2001

Make : INDIAN **Model :** SCOUT **Year :** 2001

Build Dates : 20000525 - 20000823

NHTSA CAMPAIGN ID Number : 00V251000

Date Owner's Notified: **Date Received by ODI:** **Date Added to Database:**
20000914 20000903 20000911

Manufacturer's Involved: INDIAN MOTORCYCLE COMPANY

Manufacturer's Responsible for the Recall: INDIAN MOTORCYCLE COMPANY

Manufacturer Campaign Number:

Component: TIRES:TUBE

Potential Number Of Units Affected : 418

Summary:

VEHICLE DESCRIPTION: MOTORCYCLES. THE INNER TUBE BEING USED ON THE FRONT TIRE WAS UNDER-SIZED.

Consequence:

THIS CONDITION CAN CAUSE POSSIBLE DEFLATION OF THE TUBE, INCREASING THE RISK OF A CRASH.

Remedy:

DEALERS WILL REPLACE EXISTING INNER FRONT TIRE TUBE WITH A LARGER TUBE.

Report Initiator: MFR

Vehicles Report

Regulation Part Number: **Federal Motor Vehicle Safety Standard Number:**

Notes:

CUSTOMERS CAN ALSO CONTACT THE NATIONAL HIGHWAY TRAFFIC SAFETY ADMINISTRATION'S AUTO SAFETY HOTLINE AT 1-888-DASH-2-DOT (1-888-327-4236).