

ROLLING THUNDER LLC
22231 Marine View Drive South
Des Moines, Washington 98198
(206) 870-7482
www.rollingthunderllc.com

SCOUT 2001

Make : INDIAN **Model :** SCOUT **Year :** 2001

Build Dates : 19990301 - 20010520

NHTSA CAMPAIGN ID Number : 03V039000

Date Owner's Notified: **Date Received by ODI:** **Date Added to Database:**
20030214 20030210 20030212

Manufacturer's Involved: INDIAN MOTORCYCLE COMPANY

Manufacturer's Responsible for the Recall: INDIAN MOTORCYCLE COMPANY

Manufacturer Campaign Number: IMCSB-045

Component: ELECTRICAL SYSTEM:ALTERNATOR/GENERATOR/REGULATOR

Potential Number Of Units Affected : 7947

Summary:

ON CERTAIN MOTORCYCLES EQUIPPED WITH COMPUFIRE BRAND SERIES TYPE VOLTAGE REGULATORS, IF DAMAGED, THE VOLTAGE REGULATOR CAN BECOME STUCK IN AN OPEN MODE THAT ALLOWS BATTERY VOLTAGE TO FLOW BACK THROUGH THE REGULATOR.

Consequence:

THIS CONDITION CAN POTENTIALLY CAUSE THE REGULATOR TO CATCH ON FIRE.

Remedy:

DEALERS WILL INSPECT THE MOTORCYCLE AND, IF NECESSARY, REPLACE THE REGULATOR. OWNER NOTIFICATION BEGAN FEBRUARY 14, 2003. OWNERS WHO TAKE THEIR VEHICLES TO AN AUTHORIZED DEALER ON AN AGREED UPON SERVICE DATE AND DO NOT RECEIVE THE FREE REMEDY WITHIN A REASONABLE TIME SHOULD CONTACT INDIAN MOTORCYCLE AT 1-888-899-2997.

Report Initiator: MFR

Vehicles Report

Regulation Part Number: **Federal Motor Vehicle Safety Standard Number:**

Notes:

Call 1-888-DASH-2-DOT (1-888-327-4236).