

ROLLING THUNDER LLC
22231 Marine View Drive South
Des Moines, Washington 98198
(206) 870-7482
www.rollingthunderllc.com

SCOUT 2002

Make : INDIAN **Model :** SCOUT **Year :** 2002

Build Dates : 20000214 - 20030710

NHTSA CAMPAIGN ID Number : 03V258000

Date Owner's Notified: **Date Received by ODI:** **Date Added to Database:**
20030731 20030722 20030729

Manufacturer's Involved: INDIAN MOTORCYCLE COMPANY

Manufacturer's Responsible for the Recall: INDIAN MOTORCYCLE COMPANY

Manufacturer Campaign Number: IMCSB-057

Component: EXTERIOR LIGHTING:HEADLIGHTS

Potential Number Of Units Affected : 6173

Summary:

ON CERTAIN MOTORCYCLES, THE BRACKET USED TO SUPPORT THE TEARDROP HEADLIGHT CAN CRACK, CAUSING THE BRACKET TO BREAK AND THE LIGHT TO SLIP OUT OF POSITION OR FALL OFF.

Consequence:

THIS COULD CAUSE A LOSS OF VISIBILITY TO THE DRIVER, INCREASING THE RISK OF A CRASH.

Remedy:

DEALERS WILL INSTALL A NEW BRACKET. OWNER NOTIFICATION IS EXPECTED TO BEGIN DURING AUGUST 2003. OWNERS SHOULD CONTACT IMC AT 1-888-899-2997.

Report Initiator: ODI

Vehicles Report

Regulation Part Number: **Federal Motor Vehicle Safety Standard Number:**

Notes:

CUSTOMERS CAN ALSO CONTACT THE NATIONAL HIGHWAY TRAFFIC SAFETY ADMINISTRATION'S AUTO SAFETY HOTLINE AT 1-888-DASH-2-DOT (1-888-327-4236).