

ROLLING THUNDER LLC
22231 Marine View Drive South
Des Moines, Washington 98198
206 870 7482
www.rollingthunderllc.com

SCOUT 2002

Make : INDIAN **Model :** SCOUT **Year :** 2002

Build Dates : 20010601 - 20021101

NHTSA CAMPAIGN ID Number : 02V311000

Date Owner's Notified: **Date Received by ODI:** **Date Added to Database:**
20030116 20021115 20021119

Manufacturer's Involved: INDIAN MOTORCYCLE COMPANY

Manufacturer's Responsible for the Recall: INDIAN MOTORCYCLE COMPANY

Manufacturer Campaign Number: IMCSB-050

Component: VISIBILITY:WINDSHIELD

Potential Number Of Units Affected : 5464

Summary:

ON CERTAIN MOTORCYCLES, THE FASTENERS THAT BOLT THE WINDSHIELD TO THE MOUNTING CLAMPS CAN BREAK, CAUSING THE WINDSHIELD TO COME PARTIALLY OR COMPLETELY OFF THE BIKE.

Consequence:

IF THIS HAPPENS WHILE THE MOTORCYCLE IS IN USE, THE RIDER COULD BE INJURED BY THE WINDSHIELD.

Remedy:

DEALERS WILL REPLACE THE WINDSHIELDS. OWNER NOTIFICATION BEGAN JANUARY 16, 2003. OWNERS WHO TAKE THEIR VEHICLES TO AN AUTHORIZED DEALER ON AN AGREED UPON SERVICE DATE AND DO NOT RECEIVE THE FREE REMEDY WITHIN A REASONABLE TIME SHOULD CONTACT INDIAN MOTORCYCLE AT 1-888-899-2997.

Report Initiator: MFR

Vehicles Report

Regulation Part Number: **Federal Motor Vehicle Safety Standard Number:**

Notes:

CUSTOMERS CAN ALSO CONTACT THE NATIONAL HIGHWAY TRAFFIC SAFETY ADMINISTRATION'S AUTO SAFETY HOTLINE AT 1-888-DASH-2-DOT (1-888-327-4236).