

ROLLING THUNDER LLC  
22231 Marine View Drive South  
Des Moines, Washington 98198  
206 870 7482  
[www.rollingthunderllc.com](http://www.rollingthunderllc.com)

SCOUT 2002

**Make :** INDIAN                      **Model :** SCOUT                      **Year :** 2002

**Build Dates :** 20020524 - 20020702

**NHTSA CAMPAIGN ID Number :** 02V180000

**Date Owner's Notified:**              **Date Received by ODI:**              **Date Added to Database:**  
20020816                                      20020708                                      20020722

**Manufacturer's Involved:** INDIAN MOTORCYCLE COMPANY

**Manufacturer's Responsible for the Recall:** INDIAN MOTORCYCLE COMPANY

**Manufacturer Campaign Number:**

**Component:** SUSPENSION:REAR

**Potential Number Of Units Affected :** 590

**Summary:**

ON CERTAIN MOTORCYCLES, THE REAR AXLES ARE MADE OF A MATERIAL WITH A LOWER THAN DESIRABLE YIELD STRENGTH.

**Consequence:**

UNDER REPEATED HEAVY LOADS, THE REAR AXLE COULD DEFORM CAUSING EXCESSIVE WEAR IN THE REAR WHEEL BEARINGS POTENTIALLY LEADING TO OVERHEATING AND SEIZING OF THE BEARINGS, INCREASING THE RISK OF A CRASH.

**Remedy:**

DEALERS WILL REPLACE THE REAR AXLES ON THESE MOTORCYCLES. OWNER NOTIFICATION BEGAN AUGUST 16, 2002. OWNERS WHO TAKE THEIR VEHICLES TO AN AUTHORIZED DEALER ON AN AGREED UPON SERVICE DATE AND DO NOT RECEIVE THE FREE REMEDY WITHIN A REASONABLE TIME SHOULD CONTACT INDIAN AT 1-408-846-7228.

**Report Initiator:** MFR

**Vehicles Report**

**Regulation Part Number:**      **Federal Motor Vehicle Safety Standard Number:**

**Notes:**

CUSTOMERS CAN ALSO CONTACT THE NATIONAL HIGHWAY TRAFFIC SAFETY ADMINISTRATION'S AUTO SAFETY HOTLINE AT 1-888-DASH-2-DOT