

ROLLING THUNDER LLC
22231 Marine View Drive South
Des Moines, Washington 98198
(206 870-7482
www.rollingthunderllc.com

SPIRIT 2002

Make : INDIAN **Model :** SPIRIT **Year :** 2002

Build Dates : 20000714 - 20030728

NHTSA CAMPAIGN ID Number : 03V286000

Date Owner's Notified: **Date Received by ODI:** **Date Added to Databse:**
20030825 20030804 20030807

Manufacturer's Involved: INDIAN MOTORCYCLE COMPANY

Manufacturer's Responsible for the Recall: INDIAN MOTORCYCLE COMPANY

Manufacturer Campaign Number: IMCSB-058

Component: STRUCTURE

Potential Number Of Units Affected : 6570

Summary:

ON CERTAIN MOTORCYCLES, THE WELD ATTACHING THE FENDER MOUNT TO THE FRONT FORK MAY CRACK AND BREAK.

Consequence:

THIS COULD CAUSE THE FENDER MOUNT TO FAIL RESULTING IN THE FENDER COMING INTO CONTACT WITH THE WHEEL, RESULTING IN THE RIDER TO LOSE CONTROL OF THE MOTORCYCLE, INCREASING THE RISK OF A CRASH.

Remedy:

DEALERS WILL BOLT A BRACKET ONTO EACH FRONT FORK. THIS BRACKET WILL HOLD THE FENDER MOUNT IN PLACE EVEN IF THE WELD FAILS. OWNER NOTIFICATION IS EXPECTED TO BEGIN DURING AUGUST 2003. OWNERS SHOULD CONTACT INDIAN AT 1-888-899-2997.

Report Initiator: MFR

Vehicles Report

Regulation Part Number: **Federal Motor Vehicle Safety Standard Number:**

Notes:

CUSTOMERS CAN ALSO CONT