

ROLLING THUNDER LLC  
22231 Marine View Drive South  
Des Moines, Washington 98198  
206 870 7482  
[www.rollingthunderllc.com](http://www.rollingthunderllc.com)

SCOUT 2003  
CENTENNIAL

**Make :** INDIAN                      **Model :** SCOUT  
CENTENNIAL                                      **Year :** 2003

**Build Dates :** 20010601 - 20021101

**NHTSA CAMPAIGN ID Number :** 02V311000

**Date Owner's Notified:**      **Date Received by ODI:**      **Date Added to Database:**  
20030116                              20021115                              20021119

**Manufacturer's Involved:** INDIAN MOTORCYCLE COMPANY

**Manufacturer's Responsible for the Recall:** INDIAN MOTORCYCLE COMPANY

**Manufacturer Campaign Number:** IMCSB-050

**Component:** VISIBILITY:WINDSHIELD

**Potential Number Of Units Affected :** 5464

**Summary:**

ON CERTAIN MOTORCYCLES, THE FASTENERS THAT BOLT THE WINDSHIELD TO THE MOUNTING CLAMPS CAN BREAK, CAUSING THE WINDSHIELD TO COME PARTIALLY OR COMPLETELY OFF THE BIKE.

**Consequence:**

IF THIS HAPPENS WHILE THE MOTORCYCLE IS IN USE, THE RIDER COULD BE INJURED BY THE WINDSHIELD.

**Remedy:**

DEALERS WILL REPLACE THE WINDSHIELDS. OWNER NOTIFICATION BEGAN JANUARY 16, 2003. OWNERS WHO TAKE THEIR VEHICLES TO AN AUTHORIZED DEALER ON AN AGREED UPON SERVICE DATE AND DO NOT RECEIVE THE FREE REMEDY WITHIN A REASONABLE TIME SHOULD CONTACT INDIAN MOTORCYCLE AT 1-888-899-2997.

**Report Initiator:** MFR

**Vehicles Report**

**Regulation Part Number:**      **Federal Motor Vehicle Safety Standard Number:**

**Notes:**

CUSTOMERS CAN ALSO CONTACT THE NATIONAL HIGHWAY TRAFFIC SAFETY ADMINISTRATION'S AUTO SAFETY HOTLINE AT 1-888-DASH-2-DOT