

ROLLING THUNDER LLC
22231 Marine View Drive South
Des Moines, Washington 98198
(206 870-7482
www.rollingthunderllc.com

SPIRIT 2002

Make : INDIAN **Model :** SPIRIT **Year :** 2002

Build Dates : 20011113 - 20020308

NHTSA CAMPAIGN ID Number : 02V083000

Date Owner's Notified: **Date Received by ODI:** **Date Added to Databse:**
20020319 20020321 20020327

Manufacturer's Involved: INDIAN MOTORCYCLE COMPANY

Manufacturer's Responsible for the Recall: INDIAN MOTORCYCLE COMPANY

Manufacturer Campaign Number: IMCSB-038

Component: FUEL SYSTEM, GASOLINE:STORAGE:TANK ASSEMBLY

Potential Number Of Units Affected : 907

Summary:

ON CERTAIN MOTORCYCLES, FRACTURES CAN OCCUR ON EITHER THE LEFT OR RIGHT FUEL TANK AT THE TOP OF THE JOINT WHERE THE BRACKET IS WELDED TO THE TANK BACK PLATE.

Consequence:

FUEL CAN ESCAPE FROM THE TANK, INCREASING THE RISK OF A FIRE.

Remedy:

DEALERS WILL REPLACE THE GAS TANKS WITH TANKS THAT HAVE A REDESIGNED MOUNTING BRACKET. OWNER NOTIFICATION BEGAN MARCH 19, 2002. OWNERS WHO TAKE THEIR VEHICLES TO AN AUTHORIZED DEALER ON AN AGREED UPON SERVICE DATE AND DO NOT RECEIVE THE FREE REMEDY WITHIN A REASONABLE TIME SHOULD CONTACT INDIAN MOTORCYCLE AT 1-408-846-7228.

Report Initiator: MFR

Vehicles Report

Regulation Part Number: **Federal Motor Vehicle Safety Standard Number:**

Notes:

CUSTOMERS CAN ALSO CONTACT THE NATIONAL HIGHWAY TRAFFIC SAFETY ADMINISTRATION'S AUTO SAFETY HOTLINE AT 1-888-DASH-2-DOT (1-888-327-4236).