

ROLLING THUNDER LLC
22231 Marine View Drive South
Des Moines, Washington 98198
(206) 870-7482
www.rollingthunderllc.com

CHIEF VINTAGE 2003

Make : INDIAN **Model :** CHIEF VINTAGE **Year :** 2003

Build Dates : 20030116 - 20030326

NHTSA CAMPAIGN ID Number : 03V132000

Date Owner's Notified:	Date Received by ODI:	Date Added to Database:
20030328	20030403	20030422

Manufacturer's Involved: INDIAN MOTORCYCLE COMPANY

Manufacturer's Responsible for the Recall: INDIAN MOTORCYCLE COMPANY

Manufacturer Campaign Number: IMCSB-053

Component: EQUIPMENT

Potential Number Of Units Affected : 70

Summary:

ON CERTAIN MOTORCYCLES EQUIPPED WITH FACTORY DESIGNED FRONT AND REAR ENGINE GUARDS, THE GUARDS DO NOT ALLOW SUFFICIENT CLEARANCE BETWEEN THE MOTORCYCLE AND THE GROUND DURING ROUTINE CORNERING.

Consequence:

THIS CONDITION COULD CAUSE THE RIDER TO LOSE CONTROL OF THE MOTORCYCLE, INCREASING THE RISK OF A CRASH.

Remedy:

DEALERS WILL REMOVE THE CURRENT ENGINE GUARDS AND GIVE THE OWNERS A \$250 CREDIT TOWARD THE PURCHASE OF PARTS AND ACCESSORIES FOR THEIR MOTORCYCLES. REDESIGNED ENGINE GUARDS WILL BE PROVIDED IN APPROXIMATELY 90 DAYS. THE REMOVAL AND REPLACEMENT OF THESE GUARDS WILL BE PERFORMED WITHOUT CHARGE TO THE OWNERS. OWNER NOTIFICATION BEGAN MARCH 28, 2003. OWNERS WHO TAKE THEIR VEHICLES TO AN AUTHORIZED DEALER ON AN AGREED UPON SERVICE DATE AND DO NOT RECEIVE THE FREE REMEDY WITHIN A REASONABLE TIME SHOULD CONTACT INDIAN MOTORCYCLE AT 1-888-899-2997.

Report Initiator: MFR

Vehicles Report