

ROLLING THUNDER LLC  
22231 Marine View Drive South  
Des Moines, Washington 98198  
(206) 870-7482  
[www.rollingthunderllc.com](http://www.rollingthunderllc.com)

SCOUT 2003

**Make :** INDIAN                      **Model :** SCOUT                      **Year :** 2003

**Build Dates :** 20000214 - 20030710

**NHTSA CAMPAIGN ID Number :** 03V258000

**Date Owner's Notified:**              **Date Received by ODI:**              **Date Added to Database:**  
20030731                                      20030722                                      20030729

**Manufacturer's Involved:** INDIAN MOTORCYCLE COMPANY

**Manufacturer's Responsible for the Recall:** INDIAN MOTORCYCLE COMPANY

**Manufacturer Campaign Number:** IMCSB-057

**Component:** EXTERIOR LIGHTING:HEADLIGHTS

**Potential Number Of Units Affected :** 6173

**Summary:**

ON CERTAIN MOTORCYCLES, THE BRACKET USED TO SUPPORT THE TEARDROP HEADLIGHT CAN CRACK, CAUSING THE BRACKET TO BREAK AND THE LIGHT TO SLIP OUT OF POSITION OR FALL OFF.

**Consequence:**

THIS COULD CAUSE A LOSS OF VISIBILITY TO THE DRIVER, INCREASING THE RISK OF A CRASH.

**Remedy:**

DEALERS WILL INSTALL A NEW BRACKET. OWNER NOTIFICATION IS EXPECTED TO BEGIN DURING AUGUST 2003. OWNERS SHOULD CONTACT IMC AT 1-888-899-2997.

**Report Initiator:** ODI

**Vehicles Report**

**Regulation Part Number:**      **Federal Motor Vehicle Safety Standard Number:**

**Notes:**

CUSTOMERS CAN ALSO CONTACT THE NATIONAL HIGHWAY TRAFFIC SAFETY ADMINISTRATION'S AUTO SAFETY HOTLINE AT 1-888-DASH-2-DOT (1-888-327-4236).